


# INSPECVISION REPORT

Filepath: mm.dxf  
Customer: EMO Demo  
Operator: User Name Here  
Inspection Date: 06/09/2013 (09:20:28)  
Works Order No: 123456  
Customer Order No: 789987  
Part No: 654321  
Customer Part No: 987789  
Report Summary: Items Passed: 11  
Part Thickness: Nominal: 2

Items Failed: 1  
Actual: 2.4062

Items Missing: 0  
Deviation: 0.4062

  
Extra Holes: 1



# INSPECVISION REPORT

Customer: EMO Demo  
 Operator: User Name Here  
 Inspection Date: 06/09/2013 (09:20:28)  
 Works Order No: 123456  
 Customer Order No: 789987  
 Part No: 654321  
 Customer Part No: 987789  
 Report Summary: Items Passed: 11      Items Failed: 1      Items Missing: 0      Extra Holes: 1  
 Part Thickness: Nominal: 2.000000      Actual: 2.406260      Deviation: 0.406260



Name	Entity	Datum	Dimension	Nominal	Actual	Deviation	Standard Deviation	Tolerance	Status
A	Line	Line	DistX	250	249.8546	-0.1454	0.0212	+/-0.05	Fail
B	Collection Circle	Collection Circle	Radius	12.5	12.5821	0.0821	0	+/-0.4	Pass
D	Circle	Circle	Profile	0	0.208	0.208	0.0645	+/-0.4~	Pass
E	Circle	Circle	Radius	2.5	2.6171	0.1171	0.0894	+/-0.4	Pass
F	Circle	Circle	DistX	72	71.9809	-0.0191	0.0589	+/-0.4	Pass
G	Line	Line	Perpendicularity	0	0.0545	0.0545	0.019	+/-1⊥	Pass
H	Line	Line	Degrees	90	89.855	-0.145	0.0279	+/-1	Pass
I	Circle	Circle	Dist	54.622	54.5512	-0.0708	0.0443	+/-0.4	Pass
J	Line	Line	Parallelism	0	0.036	0.036	0.0175	+/-0.4=	Pass
K	Line	Line	DistX	156	155.9603	-0.0397	0.0207	+/-0.5	Pass
L	Line	Line	Degrees	90	88.9684	-1.0316	0.0237	+/-1.5	Pass
M	Line	Line	DistY	34	33.9035	-0.0965	0.0264	+/-0.4	Pass

# INSPECVISION REPORT

Filepath: mm.dxf  
Customer: EMO Demo  
Operator: User Name Here  
Inspection Date: 06/09/2013 (09:20:28)  
Works Order No: 123456  
Customer Order No: 89987  
Part No: 654321  
Customer Part No: 987789  
Measurements: 11442  
Entities: Passed: 175  
Part Thickness: Nominal: 2

Passed: 11442  
Failed: 0  
Missing: 8  
Extra: 1  
Actual: 2.4062  
Deviation: 0.4062

